



Splice Cap Insulators

Instructions

Features

- Tough see-thru nylon
- Extra long skirts for added protection
- Snaps on easily over splice connector
- Safely insulates splice

To Install:

Place over installed splice cap and snap-on.

To Remove:

By “cold-working” retainer; Using lineman’s or other suitable pliers, squeeze skirt of insulator alternately at two points 90° apart. Pull off insulator body and cut off insulator retainer.

By “cutting”; Using diagonals or other suitable pliers, cut up side of insulator skirt. Peel off insulator body and cut off insulator retainer.

- **UL and CSA Listed** as “pressure-type wire connectors” for 2 #18 thru 4 #12 or 2 #10
- **For Use on:** 2006S or 2008S Splice Cap Crimp Connectors
- **Temperature Rating:** 105°C (221°F)
- **Voltage Rating:** UL Listed and CSA Certified for 600V on building wiring and 1000V maximum in fixtures and signs



Warning Contact with electricity can cause serious injury or death. Shut off power at the circuit breaker or remove fuse before using this product.

Safety Notice

Improperly installed electrical wiring can be dangerous and cause electrical fires. The connector chosen must be suitable for the application. Consult local building code before doing any electrical work. For assistance, refer to an instructional book or consult a qualified electrician.

IDEAL INDUSTRIES, INC.

Sycamore, IL 60178, U.S.A.
800-435-0705 Customer Assistance
www.idealindustries.com
ND 7477-1



Wire Connector
774A

LISTED



NOT CSA Certified for
Aluminum wire.



Splice Cap Insulators

Instructions

Features

- Tough see-thru nylon
- Extra long skirts for added protection
- Snaps on easily over splice connector
- Safely insulates splice

To Install:

Place over installed splice cap and snap-on.

To Remove:

By “cold-working” retainer; Using lineman’s or other suitable pliers, squeeze skirt of insulator alternately at two points 90° apart. Pull off insulator body and cut off insulator retainer.

By “cutting”; Using diagonals or other suitable pliers, cut up side of insulator skirt. Peel off insulator body and cut off insulator retainer.

- **UL and CSA Listed** as “pressure-type wire connectors” for 2 #18 thru 4 #12 or 2 #10
- **For Use on:** 2006S or 2008S Splice Cap Crimp Connectors
- **Temperature Rating:** 105°C (221°F)
- **Voltage Rating:** UL Listed and CSA Certified for 600V on building wiring and 1000V maximum in fixtures and signs



Warning Contact with electricity can cause serious injury or death. Shut off power at the circuit breaker or remove fuse before using this product.

Safety Notice

Improperly installed electrical wiring can be dangerous and cause electrical fires. The connector chosen must be suitable for the application. Consult local building code before doing any electrical work. For assistance, refer to an instructional book or consult a qualified electrician.

IDEAL INDUSTRIES, INC.

Sycamore, IL 60178, U.S.A.
800-435-0705 Customer Assistance
www.idealindustries.com
ND 7477-1



Wire Connector
774A

LISTED

