



Definition of Cold

NOTE: *Pipe should be 60° F or warmer*. PVC pipe requires slight over bending which will "pop back" a few degrees upon the release of bending pressure.

Hang up that heat gun and can that glue can. Your knee is faster and the Pipe Spring Bender makes it easy to bend 1/2" & 3/4" PVC. Add a little brute force and you can bend 1" too. Believe it!







Definition of Cold

NOTE: *Pipe should be 60° F or warmer*. PVC pipe requires slight over bending which will "pop back" a few degrees upon the release of bending pressure.

Hang up that heat gun and can that glue can. Your knee is faster and the Pipe Spring Bender makes it easy to bend 1/2" & 3/4" PVC. Add a little brute force and you can bend 1" too. Believe it!

