KLEIN TOOLS DIGITAL CLAMP METERS										
FEAT	URES	CL120	CL220	CL320	CL390	CL490	CL445	CL710	CL810	CL900
	Drop Protection	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)
	Ingress Protection	-	-	-	-	-	-	IP40	IP40	IP40
\triangle	Safety	CAT III 600V	CAT III 600V	CAT III 600V	CAT III 600V	CAT III 600V	CAT IV 600V CAT III 750V	CAT IV 600V CAT III 1000V	CAT IV 600V CAT III 1000V	CAT IV 600V CAT III 1000V
ĩ	AC Voltage (Volts)	600V	600V	600V	600V	600V	750V	1000V	1000V	1000V
v	DC Voltage (Volts)	600V	600V	600V	600V	600V	600V	1000V	1000V	1000V
Ã	AC Current (Amps)	400A	400A	400A	400A	400A	600A	600A	600A	2000A
Ā	DC Current (Amps)	_	-	_	400A	400A	-	600A	600A	2000A
Ω	Ohms (Resistance)	20MΩ	20MΩ	40MΩ	40MΩ	40MΩ	60MΩ	60MΩ	60MΩ	60MΩ
тV	AC Millivolts	٠	٠	٠	٠	•	٠	•	٠	_
mV	DC Millivolts	•	•	•	•	•	•	•	٠	•
μÄ	DC Microamps	_	_	•	٠	•	٠	_	•	_
TRMS	True RMS	-	•	•	•	•	•	•	•	•
•)))	Audible Continuity	•	•	•	•	•	•	•	•	•
-¥-	LCD Backlight	•	•	•	Backlit Reverse Contrast	Backlit Dual Hi-Vis Reverse Contrast	•	Backlit Hi-Vis Reverse Contrast	Backlit Hi-Vis Reverse Contrast	•
	Lighted Dial	_	_	-	-	-	-	٠	٠	-
°F °C	Temperature	-	-40° – 1832°F (-40° – 1000°C)	-40° - 1832°F (-40° - 1000°C)	-40° - 1832°F (-40° - 1000°C)	-40° – 1832°F (-40° – 1000°C)	-148° – 1832°F (-100° – 1000°C	-	-40° – 1832°F (-40° – 1000°C)	-
<u>N</u> Ã	Inrush Current	_	_	_	_	_	600A	-	600A	2000A
NCV	Non-Contact Voltage Testing	•	•	•	•	•	•	•	•	•
AUTO	Auto Ranging	•	٠	٠	٠	•	•	٠	٠	•
RANGE	Range Hold	•	•	•	•	•	•	•	•	•
HOLD	Data Hold	٠	٠	٠	•	•	•	٠	٠	•
►	Diode Test	-	-	•	•	•	•	•	•	•
-1+	Capacitance Test	_	_	4000 µF	4000 µF	4000 µF	6000 µF	6000 µF	6000 μF	6000 µF
Hz %	Frequency / Duty Cycle	-	-	10Hz – 60kHz	10Hz – 60kHz	10Hz - 60kHz	10Hz - 60kHz	1Hz – 500kHz	1Hz – 500kHz	1Hz – 500kHz
MAX/ Min	Max / Min	Max Only	Max Only	٠	٠	٠	٠	٠	٠	•
Δ	Relative/Zero	-	-	-	٠	•	-	•	•	•
	Magnet	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory
	Worklight	-	-	-	-	-	•	-	•	-
LERd	Lead Holder	٠	٠	٠	٠	٠	•	٠	٠	•
APO	Auto-Power Off	•	•	•	•	•	•	•	•	•
	Low Battery Indicator	•	٠	٠	•	•	•	٠	٠	•
8888 (C)	LCD Display Count	2000	2000	4000	4000	4000	6000	6000	6000	6000
	Batteries	3 x AAA	3 x AAA	3 x AAA	3 x AAA	2 x AA	3 x AAA	3 x AAA	3 x AAA	2 x AAA
	Case Included	•	•	•	•	•	•	•	•	•
	Dual Display	-	-	-	-	٠	-	-	-	-

Specifications subject to change.

© 2025 Klein Tools, Inc. Lincolnshire, IL 60069 Rev E. 06/25

KLEIN TOOLS DIGITAL CLAMP METERS										
FEAT	URES	CL120	CL220	CL320	CL390	CL490	CL445	CL710	CL810	CL900
	Drop Protection	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)	6.6 ft. (2 m)
	Ingress Protection	-	-	-	-	-	-	IP40	IP40	IP40
\triangle	Safety	CAT III 600V	CAT III 600V	CAT III 600V	CAT III 600V	CAT III 600V	CAT IV 600V CAT III 750V	CAT IV 600V CAT III 1000V	CAT IV 600V CAT III 1000V	CAT IV 600V CAT III 1000V
ĩ	AC Voltage (Volts)	600V	600V	600V	600V	600V	750V	1000V	1000V	1000V
v	DC Voltage (Volts)	600V	600V	600V	600V	600V	600V	1000V	1000V	1000V
Ã	AC Current (Amps)	400A	400A	400A	400A	400A	600A	600A	600A	2000A
Ā	DC Current (Amps)	_	-	_	400A	400A	-	600A	600A	2000A
Ω	Ohms (Resistance)	20MΩ	20MΩ	40MΩ	40MΩ	40MΩ	60MΩ	60MΩ	60MΩ	60MΩ
тV	AC Millivolts	٠	٠	٠	٠	•	٠	•	٠	_
mV	DC Millivolts	•	•	•	•	•	•	•	٠	•
μÄ	DC Microamps	_	-	•	٠	•	٠	_	•	_
TRMS	True RMS	-	•	•	•	•	•	•	•	•
•)))	Audible Continuity	•	•	٠	•	•	•	•	•	•
-¥-	LCD Backlight	•	•	•	Backlit Reverse Contrast	Backlit Dual Hi-Vis Reverse Contrast	•	Backlit Hi-Vis Reverse Contrast	Backlit Hi-Vis Reverse Contrast	•
	Lighted Dial	_	-	-	-	-	-	٠	٠	-
°F °C	Temperature	-	-40° – 1832°F (-40° – 1000°C)	-40° - 1832°F (-40° - 1000°C)	-40° - 1832°F (-40° - 1000°C)	-40° – 1832°F (-40° – 1000°C)	-148° - 1832°F (-100° - 1000°C	-	-40° – 1832°F (-40° – 1000°C)	-
<u>N</u> Ã	Inrush Current	_	_	_	_	_	600A	-	600A	2000A
NCV	Non-Contact Voltage Testing	•	•	•	•	•	•	•	•	•
AUTO	Auto Ranging	•	٠	٠	•	•	•	٠	٠	•
RANGE	Range Hold	•	•	•	•	•	•	•	•	•
HOLD	Data Hold	٠	٠	٠	•	•	•	٠	٠	•
►	Diode Test	-	-	•	•	•	•	•	•	•
-1+	Capacitance Test	_	_	4000 µF	4000 µF	4000 µF	6000 µF	6000 µF	6000 μF	6000 µF
Hz %	Frequency / Duty Cycle	-	-	10Hz – 60kHz	10Hz – 60kHz	10Hz - 60kHz	10Hz - 60kHz	1Hz – 500kHz	1Hz – 500kHz	1Hz – 500kHz
MAX/ Min	Max / Min	Max Only	Max Only	٠	٠	٠	٠	٠	٠	•
Δ	Relative/Zero	-	-	-	٠	•	-	•	•	•
	Magnet	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory	Available As Accessory
	Worklight	-	-	-	-	-	•	-	•	-
LERd	Lead Holder	٠	٠	٠	٠	٠	•	٠	٠	•
APO	Auto-Power Off	•	•	•	•	•	•	•	•	•
	Low Battery Indicator	•	٠	٠	•	•	•	٠	٠	•
8888 (CD	LCD Display Count	2000	2000	4000	4000	4000	6000	6000	6000	6000
	Batteries	3 x AAA	3 x AAA	3 x AAA	3 x AAA	2 x AA	3 x AAA	3 x AAA	3 x AAA	2 x AAA
	Case Included	•	•	•	•	•	•	•	•	•
	Dual Display	-	-	-	-	٠	-	-	-	-

Specifications subject to change.

© 2025 Klein Tools, Inc. Lincolnshire, IL 60069 Rev E. 06/25